



GARY R. HERBERT
Governor

GREG BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Inspection Report

| | |
|------------------|-------------------------|
| Permit Number: | C0070018 |
| Inspection Type: | COMPLETE |
| Inspection Date: | Monday, August 29, 2011 |
| Start Date/Time: | 8/29/2011 10:00:00 AM |
| End Date/Time: | 8/29/2011 2:00:00 PM |
| Last Inspection: | Thursday, May 19, 2011 |

Inspector: Steve Demczak

Weather: Sunny, Upper 80's

InspectionID Report Number: 2851

Accepted by: jhelfric

9/14/2011

Permitee: **CANYON FUEL COMPANY**

Operator: **CANYON FUEL COMPANY**

Site: **SOLDIER CANYON MINE**

Address: **PO BOX 1029, WELLINGTON UT 84542**

County: **CARBON**

Permit Type: **PERMANENT COAL PROGRAM**

Permit Status: **ACTIVE**

Current Acreages

| | |
|----------|------------------------|
| 6,624.64 | Total Permitted |
| 24.32 | Total Disturbed |
| | Phase I |
| | Phase II |
| | Phase III |

Mineral Ownership

- ☒ Federal
☒ State
☐ County
☐ Fee
☐ Other

Types of Operations

- ☒ Underground
☐ Surface
☐ Loadout
☐ Processing
☐ Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Permit Condition: Canyon Fuel Company has just one permit condition for the Soldier Canyon Mine; to submit water quality data in an electronic format through the Electronic Data Input web site.

Permitting Actions: None

Inspector's Signature:

Steve Demczak
Steve Demczak,

Inspector ID Number: 39

Date Wednesday, August 31, 2011

Note: This is a preliminary report. It is not to be used for enforcement purposes. It is subject to change. The final report will be submitted to the Division of Oil, Gas and Mining. Telephone (801) 538-5340 • facsimile (801) 359-3940 • TTY (801) 538-7458 • www.ogm.utah.gov



Permit Number: C0070018
 Inspection Type: COMPLETE
 Inspection Date: Monday, August 29, 2011

Inspection Continuation Sheet

Page 2 of 4

REVIEW OF PERMIT, PERFORMANCE STANDARDS, PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

| | Evaluated | Not Applicable | Comment | Enforcement |
|--|-------------------------------------|-------------------------------------|-------------------------------------|--------------------------|
| 1. Permits, Change, Transfer, Renewal, Sale | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 2. Signs and Markers | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3. Topsoil | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 4.a Hydrologic Balance: Diversions | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 4.b Hydrologic Balance: Sediment Ponds and Impoundments | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 4.c Hydrologic Balance: Other Sediment Control Measures | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 4.d Hydrologic Balance: Water Monitoring | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 4.e Hydrologic Balance: Effluent Limitations | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 5. Explosives | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 6. Disposal of Excess Spoil, Fills, Benches | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 7. Coal Mine Waste, Refuse Piles, Impoundments | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 8. Noncoal Waste | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 9. Protection of Fish, Wildlife and Related Environmental Issues | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 10. Slides and Other Damage | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 11. Contemporaneous Reclamation | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 12. Backfilling And Grading | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 13. Revegetation | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 14. Subsidence Control | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 15. Cessation of Operations | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 16.a Roads: Construction, Maintenance, Surfacing | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 16.b Roads: Drainage Controls | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 17. Other Transportation Facilities | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 18. Support Facilities, Utility Installations | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 19. AVS Check | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 20. Air Quality Permit | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 21. Bonding and Insurance | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 22. Other | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |

1. Permits, Change, Transfer, Renewal, Sale

No permitting action is currently being processed with the Division for Soldier Creek Mine. The permit will expire on Feb. 12, 2012. The SPCC plan was last inspected on December 3, 2007. The UPDES permit will expire on April 31, 2013.

2. Signs and Markers

The identification sign was on the side of the main road overlooking the sediment pond. The information addressed the requirements of the R645 Coal Rules.

3. Topsoil

The topsoil piles are located below the mine. There were no signs of wind or water erosion.

4.a Hydrologic Balance: Diversions

Diversions were opened and functioning as designed.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

Sediment pond contained a small amount of water. It is unlikely to discharge in the near future. I inspected the sediment pond and did not see any hazardous conditions. The permittee inspected the pond on April 19, 2011. There were no hazardous conditions reported.

4.d Hydrologic Balance: Water Monitoring

The water data was submitted to the Division. The site had met requirements for taking water samples in high flow year.

4.e Hydrologic Balance: Effluent Limitations

No discharge for the second quarter.

8. Noncoal Waste

The site was clear of non-coal waste material.

10. Slides and Other Damage

No slides or other damage was noticed during the inspection.

15. Cessation of Operations

No activity is taking place at mine site.

16.a Roads: Construction, Maintenance, Surfacing

It is still functioning but the concrete is breaking up.

Permit Number: C0070018
Inspection Type: COMPLETE
Inspection Date: Monday, August 29, 2011

Inspection Continuation Sheet

Page 4 of 4

16.b Roads: Drainage Controls

Diversions are functioning as designed.

18. Support Facilities, Utility Installations

There are no new facilities.

19. AVS Check

AVS checks are made in SLC.

20. Air Quality Permit

The Air Quality Permit is DAQE-334-94.

21. Bonding and Insurance

The insurance policy will expire on July 31, 2012. The bonding amount is \$1,593,000.